Under Review Notification

Raised By: Steven Drouin Product #: D412-814

Date: 19.03.27 Product Name: Replacement Crew Door Kit

		"Y" or "N" Required for Each Part								
		Do not leave blank								
Part Number (D-Part and 9-Digit) (eg. D3535-11) (eg. D3535-25) (eg. D206-642-143) (eg. RBEM324U3010101-1)	Drawing or Document & <u>Current</u> Affected Revision for each part listed	DO NOT SHIP	Red Tag/Quarantine Stock	Advise Customers	Hold all Production	Re-Work Stock	IPP Under Review (Enginer Signoff Required.)	Put Product Specifications Under Review ("Bluefiles")	Reserved ECN / URF Log Number	Instructions Relevant to Each Part (including whether CHG #'s will be affected)
D412-814-011/-015/-019	IIN-D412-814 Rev. C	Υ	Ν	Ν	Ν	Ν	Υ	Υ	19-663	CHG# 001
D412-814-012/-014/-016/-020	IIN-D412-814 Rev. C	Υ	Ν	Ν	Ν	Ν	Υ	Υ	19-663	CHG# 001
D4465-041-042	D4465 Rev. C	Υ	Ν	Ν	Ν	Ν	Υ	Υ	19-663	Drawing Update
D4467-041	D4467 Rev. D	Υ	Ν	Ν	Ν	N	Υ	Υ	19-663	Drawing Update
D4466-041	D4466 Rev.D	Υ	Ν	N	Ν	N	Υ	Υ	19-663	Drawing Update
D4582-041/-042	D4582 Rev.C	Υ	Ν	Ν	Ν	Ν	Υ	Υ	19-663	Drawing Update
D4583-041/-042	D4583 Rev.C	Υ	Ν	Ν	Ν	Ν	Υ	Υ	19-663	Drawing Update
D45885-041/-042	D4583 Rev.C	Υ	Ν	Ν	Ν	Ν	Υ	Υ	19-663	Drawing Update

Description of Issue:

On drawing D4465-041 bolt need to be changed to from dash #11 to dash #56 D4467-041 and D4466-041 Rivet change on drawings

D4465-065 need a deviation sign off for the bolt change by Engineering to ship REF CAR19-309

Replace MS21069L08nutplate on D4467 by MS21069L3 nutplate (ref PAR16-506)

Distribution:

VP Operations
Director of Operations
Director Quality Assurance
QC Coordinator

Director of Engineering Chief Engineer Engineering Project Managers Engineering Clerk Customer Support Manager Production Engineers Production Planners Purchasing Manager Technical Support
Product Manager - Solutions Provider
Supply Chain Director / Senior Buyer
Marketing Eugene